

Fire Command Center

Cobham 3308

- Booster Summary Alarm
- Donor Antenna Malfunction (VSWR)

RECTIFIER FAIL

Low Battery Capacity

MAINS or BACKUP

NEWMAR BDS-DIN-UPS 48-10


J-Box

DAS Headend

J1 on Mother Board

Model 1221-B or 1221 A Annunciator Panel

- DIP SW3- 1 OFF
- DIP SW3- 2 ON
- DIP SW3- 3 ON
- DIP SW3- 4 OFF
- DIP SW3- 5 OFF



10 k Ohm End-of-Line Resistors (Supplied with DAS Alert panel)

Cobham Amplifier & NEWMAR Charger Interface Drawing